

TOWER K



**1. Ground Floor & First Floor Flats Ceiling
Plastering Work in Progress**

TOWER J



1.External Plastering Work in Progress

TOWER L

- 
- A tall building under construction, covered in scaffolding. The building has several floors with dark window openings. Workers are visible on the scaffolding. The sky is blue with some clouds.
1. External White Wash Work in Progress
 2. External Drops Plastering Work in Progress

TOWER F

- 
1. Rainfall Texture Work in Progress
 2. Bubble With Head Cut Texture Work in Progress
 3. Drops External Plastering Work in Progress

TOWER C



1. External Plastering Work in Progress
2. Sixth Floor Pour III Column Concrete Work is Completed
3. Terrace Floor Pour I Slab Shuttering Work in Progress

TOWER G



1. Fifth Floor Pour II Slab Concrete Work is Completed
2. Fifth Floor Pour I Slab Shuttering Work in Progress
3. Third Floor Block Work in Progress

TOWER D



1. External Plastering Work in Progress
2. Fourth Floor Block Work in Progress